Safety Data Sheet

EHT-2300 Textiles- Cloth, Tape, Rope and Tubing

McAllister Mills, Inc. Revised: May 1, 2015



Section 1 – Product and Company Identification

Product Name: Continuous Aluminasilicate Fiber **Manufacturer Information:** McAllister Mills, Inc.

McAllister Mills, Inc. 173 Rainbow Circle Independence, VA 24348 (276) 773-3114

Emergency Contacts: Gary Burris

Prepared By Torri Nichols (276) 773-3114

Preparation Date: April 26, 2014

Section 2 - Hazards Identification

CAS#	Component/Ingredient	Percent by Weight
1327-36-2	Aluminasilicate Fibers	97.0-99.5
	Organic Sizing	0.5-3.0

See Section 8 of this SDS for exposure limit data for these ingredients





1



Safety Data Sheet

EHT-2300 Textiles - Cloth, Tape, Rope and Tubing

McAllister Mills, Inc.

Revised: May 1, 2015



Section 3 – Hazards Identification

Critical Hazards Not Applicable

Section 4 – First Aid Measures

Eye Contact: Wash with water until foreign matter is removed, but do not rub the eyes.

Skin Contact: Wash with cold water or with lukewarm water. Thereafter, wash with soap. Consult with medical doctor, if ache or irritation remains. **Inhalation:** If signs or symptom occur; remove person to fresh air. If no breathing, get immediate medical attention.

Section 5 – Fire Fighting Measures

Aluminasilicate Fibers: Not applicable. Not combustible.

Organic Sizing: Small amount of nitrogen oxides and hydrogen cynide. And the other substances are produced upon initial heating. These decomposition products are not expected to exceed exposure limits during recommended use procedures.

Section 6 – Accidental Release Measures

Personal Precautions: Refer to other sections of this SDS for information regarding physical and health hazards, respiratory protection, ventilation, and personal protective equipment.

Method for Clean up: Sweep carefully and collect the dust. Take due care prevent a spreading or dust.

Safety Data Sheet

EHT-2300 Textiles - Cloth, Tape, Rope and Tubing

McAllister Mills, Inc. Revised: May 1, 2015



Section 7 – Handling and Storage

Precaution for Safe Handling: To prevent the dispersal of Aluminasilicate Fiber dust, countermeasures should be enforced, such as setting up an exhaust facility at points of operation within the plant.

Respirator should be worn at places where it may be impractical to try to prevent the spread of ceramic fiber dust.

If necessary, protective eyeglasses and gloves should be worn.

Aluminasilicate Fiber dust, which has become attached to the work clothes, should be removed carefully by using a vacuum cleaner or adhesive tape without leading to a dispersal of dust.

Gargle and wash the hands after work.

Precautions for Safe Storage: Keep container dry.

Fire Prevention: Not applicable.

Section 8 – Exposure Controls / Personal Protection

Regulatory Concentration:

Mass Concentration: 2.9 mg/m